

We thank you for your purchase of this product. Please take care that this instruction manual is certainly delivered to the person in charge of operating it. For safety use of this product, please observe the following caution and also read the instructions to follow before the initial operation for proper operation of this analog indicator.

### ⚠ CAUTION

**To prevent electric shock, observe the following cautions:**

- ◆ Never make terminal connections with active lines.
- ◆ Ensure firm and tight connections to the terminals.
- ◆ Do not touch terminals while the instrument is Powered on.

**To avoid failure or malfunction of the instrument, do not use the instruments in such places where:**

- ◆ exposed to rain, water drops or direct sunlight.
- ◆ high temperature or humidity, much dust or corrosive gas.
- ◆ affected by external noise, radio waves or static electricity.
- ◆ where there is constant vibration shock.


### ■ Check at Delivery

When the TMW-80□ is delivered to you, please check that its specifications conform to your requirement and that there is no damage in transit. This instrument is carefully inspected before delivery from factory under our strict quality control program, but if you find any defect or inconvenience, please inform us of the model name and serial number of the product.


### ■ Cautions for Use

- ① This product is a precision instrument, so please take utmost care for its operation, installation or any other handling.
- ② In case of fear that this indicator suffers the surge voltage, ensure to ground one side of measuring input terminals.
- ③ Use this product within the range of its specifications and rates.

### ■ Name of Parts



### ■ Panel Cut-Out Dimension



### ■ Connections


Measuring input terminals of this instrument are M4 screw. Make correct and firm connections with crimp type terminal or like. Optimum fastening torque of the screws: 0.74 to 0.88 N·m.

### ■ Installation

Insert the instrument from the front and fasten the fixing bolts provided at two corners on the back, with the attached nuts. Optimum fastening torque of the nuts: 0.36 to 0.48 N·m.

### ● Measuring Input Terminals

DC voltmeter / DC ammeter / Receiving meter  
Connect the measuring input with correct polarity, with an accessory if it is designated.



### ■ Operation

- ① Confirm the rated input and that the connection of the terminals are correctly made.
- ② Before starting the measurement, confirm that the pointer indicates zero position.  
(When the rated input is DC 4 to 20 mA or DC 1 to 5 V, zero corresponds to DC 4 mA or DC 1 V which may be input to the measuring input terminals by standard voltage generator or else.)  
If there is deviation from zero, adjust it to 0 turning a zero-adjuster provided on the front of the instrument.

### Contact Information

Name : Tsuruga Electric Corporation  
Address : Taiyo Seimei Osakaminami Building 5F  
1-10-6, Abikohigashi, Sumiyoshi-ku, Osaka, Japan, 558-0013  
E-mail : ft.info@tsuruga.co.jp